

平成26年度 全項目検査結果

Table with columns for '検査項目' (Inspection Items) and '検査成績' (Inspection Results). The table is organized by '水道' (Water Supply) and '地区' (Area), including locations like '湯沢保育園' (Tsuzae Daycare) and '芝原' (Shirahara). It lists various water quality parameters such as '残留塩素', 'クロロホルム', and 'ニトロクロロエチレン' with their respective values and compliance status (e.g., '0.35', '0.001未満').